# Manufacturer Information

For users regarding firmware and hardware updates (in accordance with the NAMUR 53 recommendation)

# 1 Type of device

- Field device / signal processing device
- □ Monitoring / operating system

Manufacturer	:	Endress+Hauser	
Product	:	HART <sup>®</sup> - DIN rail temperature transmitter	
Part number / Order code	:	TMT122/112-xBxxx; TMT122/112-xCxxx; TMT122/112-xDxxx; TMT1227112-xExxx; TMT122/112-xFxxx	
Communication / Interface	:	Communication	Device Type
		HART <sup>®</sup> 5	0x00C9

### 2 Firmware, Hardware I

Type of change:

➢ Firmware version
 ➢ Hardware I revision
 Old version / revision
 : DeviceRel: 1.00.11; HW: 08
 New version / revision
 : DeviceRel: 1.01.00; HW: 09

How can the old Firmware version / Hardware I revision number be identified:

Nameplate, parameter in configuration software, HART command 0

Description of the modification with respect to the old Firmware version / Hardware I revision:

The change only affects variants TMT122/112-xBxxx; TMT122/112-xCxxx; TMT122/112-xDxxx; TMT122/112-xExxx; TMT122/112-xFxxx. Electronic components have been changed, making a Device necessary. The hardware version has been increased at the last digit.

# 3 Compatibility (Firmware, Hardware I)

Is the new Firmware version compatible with the previous version, the installed device drivers, the operating tool compatible / is the new Hardware I revision compatible with the previous revision?

□ Yes

 $\boxtimes$  No, description:



The TMT122/112-xBxxx; TMT122/112-xCxxx; TMT122/112-xDxxx; TMT122/112-xExxx; TMT122/112-xFxxx versions are identical to TMT122/112-xAxxx; TMT122/112-x1xxx; TMT122/112-x2xxx; TMT122/112-x3xxx; TMT122/112-x4xxx from the functional and integration side, but have NO SIL conformity.

Is a Firmware / Hardware I update generally recommended?

☐ Yes, reason:

The firmware update / hardware exchange can be performed by means of:

- Replacement of electronic circuit boards; communication and amplifier module (This procedure is described in the operating instructions of the measuring system).
- Flashing the new firmware by means of; service or configuration program

#### ⊠ No, reason:

An update to firmware version 01.01.00 is not possible.

### 4 Instruction manual

Is a new instruction manual required because of the changes in point 2?

☑ Yes□ No

Which manual corresponds to the new Firmware version / Hardware I revision:

 The new instruction manuals can be downloaded from the Internet:

 www.endress.com
 - area "DOWNLOADS"

 - enter the device details and type of manual

## 5 Price

Has the price of the device changed?

Yes, new list price and update costs (without installation) are attached

🖾 No